

Skagit County South Fork Bridge
Deck Repair



Elevation View

Skagit County South Fork Bridge
Deck Repair



Deck View

Skagit County South Fork Bridge
Deck Repair



Typical Deck Condition

Pierce County Puyallup River
Deck Repair



Elevation View

Pierce County Puyallup River
Deck Repair



Deck View

Pierce County Puyallup River
Deck Repair



Typical Deck Condition

Pierce County Puyallup River
Deck Repair



Typical Deck Condition

City of Sumner Stuck River Bridge
Deck Repair, Painting



Elevation View

City of Sumner Stuck River Bridge
Deck Repair, Painting



Deck View

City of Sumner Stuck River Bridge
Deck Repair, Painting



Deck & Sidewalk Condition

City of Sumner Stuck River Bridge
Deck Repair, Painting



Traffic Damage

City of Sumner
Stuck River
Bridge
Deck Repair, Painting



Traffic
Damage

City of Sumner Stuck River Bridge
Deck Repair, Painting



Deck Joint

Pierce County Anderson Island
Electrical Mechanical



View of Damaged Ferry Slip

Pierce County Anderson Island
Electrical Mechanical



Damaged Ferry Slip Apron

Pierce County Anderson Island
Electrical Mechanical



Collapsed Apron Support

Pierce County Anderson Island
Electrical Mechanical



Ferry Slip Apron Collapsed
onto Pontoon

Lewis County Boistfort
Scour Mitigation



Elevation View

Lewis County Boistfort
Scour Mitigation



Deck View

Lewis County Boistfort
Scour Mitigation



Bank Erosion at Pier

Lewis County Boistfort
Scour Mitigation



Bank Erosion at Piles

Lewis County Boistfort
Scour Mitigation



Bank Erosion at Piles

Pend Oreille County Ione Bridge



Elevation View

Pend Oreille County Ione Bridge



Deck View

Pend Oreille County Ione Bridge



View of Damaged Pile

Pend Oreille County Ione Bridge



View of Scour Problem

Pend Oreille County Ione Bridge



View of Split Stringer

Pend Oreille County Ione Bridge



Deck Condition

Ferry County Toroda Bridge
Bridge Strengthening



Elevation View

Ferry County Toroda Bridge
Bridge Strengthening



Deck View with Posting

Ferry County Toroda Bridge
Bridge Strengthening



Substructure

Ferry County Toroda Bridge
Bridge Strengthening



Hanger Assembly

City of Sumner Stuck River Bridge
Deck Repair, Painting



Elevation View

City of Sumner Stuck River Bridge
Deck Repair, Painting



Deck View

Lewis County Packwood
Paint



Elevation View

Lewis County Packwood
Paint



View of Traffic Damage

Lewis County Packwood
Paint



Rust Freckled Paint

Lewis County
Packwood
Paint



Rust
Freckled
Paint on
Stringers

Lewis County Packwood
Paint



View of Failing Paint System